Order-No.: DD+DIS260.00E

1 Piece T9YVZ MA1

September 2000

Field Service Bulletin No. 3 for
ADC System Components Type 4406

	Classification				When		
	Safety relevant	Reliability	New function	Information	Immediately	Next service	As required
for all items				X			

List of Contents

1 General Information on PRID 1.1.11 1
1.1 Software Prerequisites: 1
1.2 Required Time for the Upgrade 1
1.3 Order No.: EB+4406.0731 2
2 Solved Problems from PRID 1.1.10 to PRID 1.1.11 2
3 What's new from PRID 1.1.10 to PRID 1.1.11 2
4 Known Bugs not solved yet (PRID 1.1.11) 3

1 General Information on PRID 1.1.11

PRID 1.1.11 is available now and replaces PRID 1.1.10.
PRID 1.1.10 can no longer be ordered.

1.1 Software Prerequisites:

ADC Compact Digitizer:	≥ COP_1215; (CM+9.5145.1050.2)
ADC Solo Digitizer:	≥ SOL_1108; (CM+9.5155.1050.2)
ADC Compact Processing Station – MIMOSA SW:	≥ VIPS1.0.09

1.2 Required Time for the Upgrade

Less than 15 minutes.

1.3 Order No.: EB+4406.0731

Scope of delivery of software upgrade kit PRID 1.1.11

- 1 x CD ROM — PRID 1.1.11
- 1 x Floppy disk — Language files LNG.1.0.05 for PRID ≥ 1.1.05
- 1 x Documentation — Upgrade procedure (DD+DIS238.00E)
- 4 x License card — For Identification SW, for Preview SW, for RIS-link Toolkit SW, for Auto-routing SW

2 Solved Problems from PRID 1.1.10 to PRID 1.1.11

- If the ID-screen was minimized manually, it did not pop up on insertion of a cassette. With PRID.1.1.11 a small window pops up telling you to maximize the ID-screen. However, it is not possible to directly open the minimized ID-screen due to restrictions in Java.
- Sorting of the worklist entries is possible on every column now (even on the first one).
- It can be configured which field should be selected first in the ID-screen when a cassette is inserted. This works now also for fields that provide a selection list (e.g. Radiologists).
- If in the worklist an entry was searched for by pressing the first character and no entry was found the cursor jumped to the first entry in the worklist. This was very annoying. Now the cursor remains where it was.
- All items coming from RIS on series level were refused. Instead, defaults were used (e.g. laterality, body part, cassette orientation, sensitivity, ap/pa, destinations, etc). Now all items coming from RIS are accepted.
- UI With Ris: if radiologist, exam, ... attribute is not available from RIS, the ID-screen displayed the first entry from the selection list. This is changed now in a way that always the last entry is displayed (like it was in PRID.1.1.07).
- In the Preview the menu item “Change Language” has been added.
- The “Time Host” feature does work now.

3 What’s new from PRID 1.1.10 to PRID 1.1.11

- Support of cassettes with asymmetric scan size. This cassettes require a special initialization in the initialization menu. This has been introduced with PRID.1.1.11. Please note that asymmetric scanning requires a certain digitizer software (for ADC COMPACT → COP_13xx and for ADC SOLO → SOL_12xx). If you do not have that software installed, the cassette will be refused by the digitizer.
- Support of mammography cassettes. This cassettes require a special initialization in the initialization menu. This has been introduced with PRID.1.1.11. Please note that mammography cassettes require a certain digitizer software (for ADC COMPACT → COP_13xx and for ADC SOLO → SOL_xxxx). If you do not have that software installed, the cassette will be refused by the digitizer.
- Reloading of the worklist also works now with worklist based on an ASCII file.

4 Known Bugs not solved yet (PRID 1.1.11)

- If no data is entered in the birth date field in the ID-screen it will default to 01-01-0001.
- License numbers are not kept over an upgrade to PRID1110. They have to be re-entered during / after installation.
- The history list is not refreshed right away if an item is deleted.
- Logfiles cannot be deleted from the Service Menu of the ID-application. If necessary this has to be done via NT-Explorer.
- When receiving images, the license window is minimized and is not accessible anymore. Before you license any option make sure that nobody is sending images to that PRID-Station.